

FIG. 1




FIG. 2

668250" 44422660




FIG. 3




FIG. 4A




FIG. 4B




FIG. 5A




FIG. 5B




FIG. 6

0932244-052899
668250-442250

ADDRESS (CORRESPONDING TO VALUE OF TIME COUNTER)	CORRELATION LEVEL DATA
0 0 0 0 0 0 0 1	1 3
0 0 0 0 0 0 1 0	1 9
0 0 0 0 0 0 1 1	2 7
0 0 0 0 0 1 0 0	4 5
⋮	⋮
0 1 0 0 0 0 0 1	4
0 1 0 0 0 0 1 0	4
⋮	⋮

FIG. 7




FIG. 8




FIG. 9




FIG. 10




FIG. 11


09322444-052899
668250-442260

COMMUNICATION CHANNEL	PRIORITY LEVEL
# a	4
# b	3
# c	3
⋮	⋮
# n	2

FIG. 12

668250-4422E60

DELAY PROFILE
CHARACTERISTIC
AT TIME T_1



DELAY PROFILE
CHARACTERISTIC
AT TIME T_2





FIG. 13






FIG. 15




FIG. 16




FIG. 17




FIG. 18




FIG. 19




FIG. 20




FIG. 21




FIG. 22




FIG. 23